

Original Comment:

31/10/03

When plugged into shore power, the hot water on our Bav 32 never seems to get really hot. It's ok, just about hot enough for washing up etc without needing to add any cold.

Is this the norm and, if not, is there a thermostat on the heater? I've looked at the manual but it really only seems to deal with fitting the unit, not adjusting it.

Andy Horwood (B32 Minna)

Replies:

We tried to get an immersion heater fitting for our Ardic Calorifier, but have been advised that they are no longer available. Would be interested to know what make your calorifier is.

Assuming that the fitting is similar to a domestic immersion heater, I would have thought that there was a temperature setting adjuster on the cap of the element.

Regards,

Carole (BAV 43 MICA)